



Screen Fillers and Stencil Treatments

Screen Fillers

Xtend Red and **Green Fillers** are easily applied and removed, water soluble, flexible screen fillers. They have excellent solvent and abrasion resistance when used with UV and solvent-based inks, lacquers and varnishes.

- High viscosity - reduces seepage through mesh.
- Excellent spreading properties.
- Economical in use, may be thinned with water.
- For the artist working directly on the screen, drybrush, stippled and similar effects can be achieved and corrections made.

Filler WR is resistant to water-based inks and to Xtend Screen Cleaner Aqua. Filler WR can be removed using any of the other Xtend Screen Cleaner products (see information sheet 'Xtend Screen Cleaners').

- Highly flexible.
- Excellent water and abrasion resistance.
- Suitable for masking, spotting and re-touching water resistant stencils
- Highly resistant to water-based UV, water-based textile and water-based graphic inks.

Universal Filler is a two-pack water-based product, which is resistant to all ink systems and can be used for edge masking and spotting out stencils.

- Resistant to solvent, UV, water-based UV, water-based graphic, plastisol and water-based textile inks.
- Very low odour.
- Removable with the stencil using one of the Xtend Strip decoating products.

Stencil Treatments

Stencil treatments are used to improve the durability of Dirasol Stencils when used for exceptionally long print runs or for the production of library stencils. Finished stencils can be treated with Sericure for extra water resistance or with Dirasol Super Hardener for improved abrasion resistance and the maximum resistance to solvent and water.

Sericure - Stencil Waterproofing Agent

- Enhances water resistance of all Dirasol emulsions.
- Designed for use with water-based textile inks.
- Stencils treated with Sericure are also suitable for most other applications requiring water resistant stencils, such as printing water-based adhesives and ceramic colours.
- Stencils can be decoated.

Dirasol Super Hardener - Post Hardening Solution

- Maximum durability to all ink systems.
- Easy to use 50/50 mixing ratio.
- Can be used on Nylon or Polyester Mesh.
- Non corrosive.
- No fogging of unexposed screens when dried together in the same cabinet.

Instructions for Use

Green/Red Filler and Filler WR:

To mask open mesh area between stencil and frame:

1. Pour a small quantity of filler onto the outside of the screen and spread across the open area with a stiff piece of card or a plastic spatula.
2. Remove any surplus filler from the underside which may have seeped through.
3. Allow to dry - this may be accelerated by using a warm air fan.
4. With coarse meshes a second application may be necessary on the underside of the mesh to ensure complete sealing.

For spotting out or repairs to stencils:

1. Examine new stencils and masked screens for pinholes. These may be spotted out with a brush. Filler WR is easily washed out of brushes using 'Xtend Screen Cleaner' or 'Screen Wash Universal'. Green/Red Filler only requires water.
2. If a stencil develops a small hole during a print run, thoroughly clean away all ink from the area and spot out with a brush. Drying can be accelerated using warm air.

To remove Green/Red Filler:

1. Thoroughly clean screen of ink residue and allow solvent to evaporate.
2. Wash away filler with cold water or remove with a high pressure stripper.

To remove Filler WR:

1. Apply 'Xtend Screen Cleaner' to both sides of the screen using a rag or brush, rubbing until all residues of ink and filler are completely removed.
2. Thoroughly rinse with water before decoating the stencil.

Remove the stencil with the appropriate Xtend reclaiming product. See the 'Stencil Decoating and Mesh Stain Removal Chemicals' Product Information Sheet.

To avoid the possibility of mesh blockage, Filler WR filler should be completely removed before applying stencil decoating chemicals.

IMPORTANT: Filler WR will not resist Screen Wash Universal or other similar wash-up solvents. These should not be used unless the screen is being washed up prior to decoating.

During the print run and also after the run where stencils are to be reused, inks may be washed up with either water (for water-based UV and water-based textile inks) or Screen Cleaner Aqua (for water-based jet drying graphic inks).

Instructions for Use

Universal Filler

Add the activator to the base and mix thoroughly. Leave to de-gas before use. For optimum durability the mixed filler should be left overnight before using. Once mixed the filler has a shelf-life of two

months although it may thicken slightly with age. Although still advisable to stir before use, for shorter print runs the filler can be used without adding activator. This will also make it easier to decoat. For masking open mesh area between stencil and frame.

1. Pour a small quantity of Universal Filler onto the substrate side of the screen and spread with a stiff piece of card or plastic. Coarse mesh may require a second application.
2. Universal filler can be air dried but its durability will be optimised by drying in warm air (40°C). Care should be taken to ensure filler is not accidentally splashed into open areas of the stencil. However, if this does happen, it can be removed with water when wet or Xtend Strip when dried.

For spotting out or repairs to stencil

1. Examine new stencils for pin-holes and spot out with a brush containing Universal Filler. Brushes can be washed out in water but if filler is allowed to dry in the brush a solution of Stencilstrip will be needed.
2. If a stencil develops a small hole during the print run, thoroughly clean away all ink from the area and spot out using a brush.

The filler will be decoated with the stencil emulsion using one of the Xtend Stencilstrip products.

Instructions for Use

Sericure

1. Apply Sericure to both sides of the dry stencil using a soft brush or sponge.
2. Allow stencil to air dry horizontally at room temperature.
3. Finish drying in a hot air cupboard at 60°C for at least ten minutes. Longer hot air drying will further improve the resistance of the stencil.

For best results Sericure should be used with water-resistant Dirasols, their durability will be considerably extended after treating with Sericure. **Sericure is only suitable for use with polyester mesh.** Stencils treated with Sericure can be difficult to decoat, but this can be achieved using Stencilstrip in conjunction with a high pressure water gun.

Instructions for Use

Dirasol Super Hardener

1. Mix Dirasol Super Hardener, Parts A and B, in equal proportions by weight or volume. Once mixed, the solution has a shelf-life of approximately 2 weeks.
2. Apply Dirasol Super Hardener to both sides of the dry stencil using a soft brush or sponge.
3. For maximum stencil durability, allow treated stencil to stand overnight;
- or -
Leave to stand at room temperature for 1 hour and then place in front of hot fans (40-50°C) for a further hour.

Stencils, correctly treated with Dirasol Super Hardener, must be

considered non-decoatable.

Standard Packing

Green Filler	
FIQ41	1 and 5 ltr containers
Red Filler	
FIR67	1 and 5 ltr containers
Filler WR (Water Resistant Screen Filler)	
WRG20	5 ltr containers
WRG20	1 ltr containers
Universal Filler:	
FISW1/6	6 x filler and activator to make 6 litres
FISW1/1	Filler and activator to make 1 litre
Sericure:	
SCK81/1	1 ltr container
SCK81/5	5 ltr container
Dirasol Super Hardener:	
JHH76/1	1 ltr container - Part A
JHH77/1	1 ltr container - Part B
JHH76/5	5 ltr container - Part A
JHH77/5	5 ltr container - Part B

Storage

Always replace lids after use and store in a cool place.

Safety and Handling

Green/Red Filler, Filler WR, Universal Filler, Sericure and Dirasol Super Hardener :

- Are formulated to be free from any (toxic) carcinogenic, mutagenic or reprotoxic chemicals.
- Do not have a flashpoint and are therefore exempt from the Highly Flammable Liquid Regulations.

Comprehensive information on the safety and handling of these products is given in the appropriate Sericol Safety Data Sheets, available upon request.

Environmental Information

Green/Red Filler, Filler WR, Universal Filler, Sericure and Dirasol Super Hardener:

- Do not contain ozone depleting chemicals as described in the Montreal Convention.

Green/Red Fillers:

- Are water-based and therefore considerably reduce any adverse effect of solvents on the environment.
- Are formulated free from aromatic hydrocarbons which are known to have an adverse effect on the environment.

SERICOL
More than ink...Solutions.



Sericol Limited Pysons Road Broadstairs Kent CT10 2LE England
Telephone: (01843) 866668 Fax: (01843) 872074

UK Sales - Tel: (020) 8391 8010 Fax: (020) 8391 8008
Email: UKsales@Sericol.com

Customer Service Centres - Tel: 0845 084 89 89
Birmingham, Bristol, Broadstairs, Gateshead, Glasgow,
Leeds, London-North, London-South, Warrington.

Technical Helpline - Tel: 0845 770 80 70

Export Sales
Pysons Road Broadstairs Kent CT10 2LE England
Tel: +44 (0)1843 866668 Fax: +44 (0)1843 872122
Email: Exportsales@Sericol.com

www.sericol.com